
RIDER 850 - THE 1988 MODEL

The 1988 model of the Rider 850 features a new gearbox. Since the gearbox has now been reinforced, and has four carrier keys where the old gearbox had only two, the friction in the gear shift mechanism is greater. This can sometimes make it difficult to disengage a gear, especially on a slope. The drive belt tries to become circular when the gears are disengaged, and is thus touching the drive wheels of both the engine and the gearbox. This results in the gear shift mechanism becoming "prestresses" and makes it difficult to engage the next gear.

How to remedy the problem: Fit belt guides as shown in Sketch A. The plates (1) and (2) should be fitted to the fastenings in the steering spindle for the steering cables, A further plate (3) should be fixed to the fastening for the clutch cable as shown in Sketch B. The bolt (4) should be fitted in the groove in the disengagement arm, and then adjusted so that the distance between the head of the bolt and the belt is 5 mm when a gear is engaged. The bolt should be at the same height as the belt.

Fitting these belt guides produces complete disengagement of the gearbox drive wheel, and makes the gears easy to change.

Sketches C and D show the plates that should be fitted to the fastenings in the steering spindle.



7: X 88.008-26 1.15 5-88

For Husqvarna Parts Call 606-678-9623 or 606-561-4983

