



Service Bulletin

Date: December 11, 2002

Product Line: ATV

Bulletin No: 2003-2-03

Subject: Carburetor Contamination

Affected Models / VIN:

All 2002 90 Y-12 Youth Models

Model No. A2002ATB2BUSR (Red)

Model No. A2002ATB2BUSG (Green)

REISSUE

■NOTE: Original Service Bulletin 2003-2-03, dated December 9, 2002, contained an error in the Warranty section. For Manual Claims, you were incorrectly instructed to enter 0303 in the Complaint section. The correct entry should be 303A.

All other information in the original bulletin is correct. Please discard original Service Bulletin 2003-2-03, dated December 9, 2002, and replace it with this reissue Service Bulletin.

Condition: It has been determined that Air Intake Boot (p/n 3301-069) and Purge Hole Plug (p/n 3301-169) may deteriorate causing unwanted foreign material to enter the carburetor system. This condition will cause the engine to not run properly.

Solution: Install Intake Boot Update Kit (p/n 0437-028) according to the instructions included in the kit. If you have an affected ATV at your dealership that still has the affected parts installed, do not sell the ATV until the existing parts have been replaced.

All registered owners of an affected ATV will be sent a letter concerning this issue. They will be instructed to contact an authorized Arctic Cat ATV dealer to have the necessary service work completed.

Parts: Order an appropriate number of Intake Boot Update Kit (p/n 0437-028) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.3 hr will be paid per affected ATV.

Only one vehicle identification number (VIN) can be entered per claim. Do not enter a group claim.

CatTracker Claim - Enter BA200303 in the Complaint section.

Manual Claim - Enter 303A in the Complaint section



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1202