



Service Bulletin

Date: December 27, 2000

Bulletin No: 2001-1-15

Product Line: Snowmobile

Affected

Model(s): 2001 Z 440 Sno Pro
& ZR 440 Sno Pro

VIN: Not Applicable

Subject: Inside Track Lugs/
Front Arm Shock Bracket

Condition: It has been determined that the inside track lugs are coming into contact with the edges of the front arm shock bracket. This condition will cause unwanted wear on the track.

Solution: Install the track guide per instructions. Contact the owners of the affected snowmobiles sold through your dealership and make arrangements for the necessary service work to be completed. Also make sure to complete the necessary service work on affected snowmobiles still at your dealership.

■ **Note: All racers have been sent the appropriate number of track guides. Do not order track guides for racers.**

Parts: Order the appropriate number of Track Guide Update Kit(s) (p/n 0637-209) including installation instructions through normal parts-ordering channels. Your dealership Parts Account will be billed for the parts and then credited upon receipt of Warranty Claim Form(s) from your dealership.

Warranty: A labor allowance of 0.8 hr will be paid per affected snowmobile.

■ **Note: No labor or parts allowance will be made for racers.**

Enter 2001-1-15 in the Failure Code section of the Warranty Claim Form.

■ **Note: This bulletin expires December 27, 2002**



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1200



Bulletin de service

Date: Le 27 décembre 2000

Modèle(s)

Numéro de bulletin: 2001-1-15

Affecté(s): Z 440 Sno Pro et
ZR 440 Sno Pro 2001

Ligne de production: Motoneige

NIV: Ne s'applique pas

Sujet: Guides internes de chenille et
tasseau d'amortisseur de bras
avant

Condition: Il a été déterminé que les guides internes de chenille entrent en contact avec les rebords du tasseau d'amortisseur de bras avant. Cette condition peut provoquer une usure importante de la chenille.

Solution: Installez le guide de chenille selon les instructions. Veuillez communiquer avec les propriétaires de motoneiges concernées qui ont été vendues à votre concession et prenez les arrangements pour que le travail de service nécessaire soit complété. De plus, veuillez vous assurer de compléter le travail de service des motoneiges en question qui sont encore à votre concession.

■ **Remarque: Le nombre approprié de guides de chenille a été envoyé à tous les coureurs. Veuillez ne pas commander de guides de chenille pour les coureurs.**

Pièces: Veuillez commander le nombre approprié de trousse de mise à jour de guide de chenille (n/p 0637-209) incluant les instructions pour l'installation en passant par les voies de commande normales. Votre compte de pièces de concession sera facturé pour les pièces et ensuite crédité lors de la réception du(des) formulaire(s) de réclamation de garantie de votre concession.

Garantie: Une allocation de main-d'oeuvre de 0,8h sera payée par motoneige concernée.

■ **Remarque: Aucune allocation de main-d'oeuvre ou de pièces ne sera accordée pour les coureurs.**

Veuillez inscrire 2001-1-15 à la section code de panne sur le formulaire de réclamation de garantie.

■ **Remarque: Ce bulletin prendra fin le 27 décembre 2002.**



Imprimé aux États-Unis



® TM Marques déposées d'Arctic Cat Inc., Thief River Falls, MN 56701



1200