

Service Bulletin

## Date: July 24, 2006

## Product Line: ATV

Bulletin No: 2007-2-01

Subject: Clutch Cover Erosion

## **Affected Models/VIN:**

All 2005 and 2006 DVX 400 Models

(p/n 0437-052).

- Condition: It has been determined that the existing magnesium clutch cover in the sealing area adjacent to the water pump cavity may erode, and this erosion can affect the sealing ability of the clutch cover and in extreme cases allow engine coolant to contaminate the oil.
  Solution: Replace the existing magnesium clutch cover with new Aluminum Clutch Cover Update Kit
- **Parts:** Order an appropriate number of Aluminum Clutch Cover Update Kits (p/n 0437-052) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

■ NOTE: The oil and coolant necessary to install the above kit is not included in the kit; however, your dealership will be reimbursed a total of \$14.00 (U.S.) per vehicle for the oil and coolant when your claim is submitted.

**Warranty:** A labor allowance of 1.4 hr will be paid per affected vehicle.

■ NOTE: Please remember that when submitting a claim, make sure to always enter the current mileage of each affected vehicle. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on vehicles with warranty claims is important.

## 

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to July 24, 2007. All warranty claims directly related to this issue will not be honored after July 24, 2007 without prior approval.









Printed in the U.S.A. ®™Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701