



# Service Bulletin

**Date:** September 6, 2002

**Product Line:** Snowmobile

**Bulletin No:** 2003-1-06

**Subject:** Recoil Starter Rope Guide

## Affected Models / VIN:

All 2003 Mountain Cat 900 (Early Build Model Only)

Model No. S2003MCJSEUSB

---

**Condition:** It has been determined that existing Recoil Starter Rope Guide (p/n 0707-705) on the affected model may not adequately guide the recoil rope. This condition will allow the recoil starter rope to come into contact with the brake components causing premature wearing of the recoil rope.

**Solution:** Install new Recoil Starter Rope Guide Update Kit (p/n 0637-231) per kit instructions

**Parts:** Order an appropriate number of Recoil Starter Rope Guide Update Kit (p/n 0637-231) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

■ **NOTE:** Recoil Starter Rope Guide Update Kit (p/n 0637-231) will be available on approximately November 1. Any orders placed prior to this date will be shipped as soon as the kits are available.

**Warranty:** A labor allowance of 0.4 hr will be paid per affected snowmobile.

Only one vehicle identification number (VIN) can be entered per claim. Do not submit a group claim.

CatTracker Claim - Enter BS200306 in the Complaint section

Manual Claim - Enter 0306 in the Complaint section



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0902