

# Service Bulletin

Bulletin No: 2005-1-07 Subject: Taillight Lens Compliance

## **Affected Models/VIN Range:**

Various 2005 Models (See list enclosed with this bulletin)

**Condition:** Recent testing conducted by Transport Canada revealed that the reflex section of Taillight Lens (p/n

0609-090) used on various 2005 Arctic Cat snowmobile models does not comply with the specifications set forth by the Snowmobile Safety and Certification Committee. See list of affected snowmobiles

enclosed with this bulletin.

**Solution:** In order to comply with the SSCC certification program, it is necessary to install a replacement lens on

all affected models. All registered owners of affected snowmobiles will be notified concerning this issue

and will be sent a replacement lens for them to install.

■ NOTE: Owners who have had their snowmobiles registered through February 20, 2005, will be notified and sent a replacement lens. All remaining snowmobiles (those with owner registrations submitted after February 20, 2005) should be serviced by an authorized Arctic Cat snowmobile dealer.

If your dealership has any affected snowmobiles at your dealership, please install the replacement lens prior to releasing the snowmobile to a customer.

Parts: Orde

Order an appropriate number of new Taillight Lens (p/n 0609-090) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

■ NOTE: Parts inventory of Taillight Lens (p/n 0609-090) ordered between March of 2004 and January of 2005 may be affected and should be returned to Arctic Cat. Return to the Arctic Cat Product Service and Warranty Department upon receipt of a parts return letter. Do not use any inventory of Taillight Lens (p/n 0609-090) ordered between March of 2004 and January of 2005 for service work related to this bulletin.

**Warranty:** 

A total labor allowance of 0.2 hr will be paid per snowmobile. Cat Tracker Claim: Enter BS200507 in the Complaint section. Manual Claim: Enter 0507 in the Complaint section.

■ NOTE: Please remember that when submitting a claim, make sure to always enter the current mileage of each affected snowmobile. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on snowmobiles with warranty claims is important.

#### **ATTENTION**

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to February 21, 2006. All warranty claims directly related to this issue will not be honored after February 21, 2006.

## Affected Snowmobile Models (All 2005 models equipped with Taillight Lens (p/n 0609-090)

### **Model Number**

## **Description**

### **International Models**

S2005ACFTOOSB	2005 T660 Touring OS Black
S2005ACFTTOSB	2005 T660 Turbo Touring U.S. OS Black
S2005ACFTBOSR	2005 Turbo ST OS Red
S2005PAAWROSB	2005 Panther 370 r OS Black
S2005PADFCOSB	2005Panther 570 OS Black







