



Service Advisory

Date: July 22, 2002

Product Line: ATV

Advisory No: SAA302

Subject: Tie Rods Contacting Rims

Affected Models/VIN:

All 2002 ATV Models (Excluding the Y-12 Youth ATV & SBS 1000 Utility)

■NOTE: THIS IS NOT A WARRANTY ISSUE.

Arctic Cat has received some reports of the tie rods coming into contact with the front rims when the wheels are turned to the maximum turning position. This condition is causing damage to the tie rods from interference between the tie rods and the rims.

■NOTE: THIS ADVISORY IS NOT RELATED TO ANY CURRENT SERVICE BULLETIN/WARRANTY ISSUE. THIS ADVISORY IS INTENDED ONLY FOR YOUR INFORMATION TO BETTER SERVICE YOUR CUSTOMERS.

Through normal use, the front wheels may come out of alignment. If a customer brings an affected ATV to your dealership with the above condition, make arrangements with the customer to have the front wheels aligned.

■NOTE: The front wheels must be aligned to a specification of 1/4 in. toe-in per wheel in order to eliminate the interference between the tie rods and the rims.

Refer to Section 8 of the 2002 Arctic Cat ATV Service Manual for procedures.

Thank you for your cooperation in this matter.

Sincerely,

Product Service Department

Arctic Cat Inc.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0702