



Service Advisory

Date: October 7, 2002

Product Line: ATV

Advisory No: SAA304

Subject: Compression Specifications/ 90 Model

Affected Model:

All 2002 and 2003 90 ATV Models

It has been brought to our attention that the compression specifications listed in the 2003 ATV Y-12 Youth Service Manual (p/n 2256-652) are incorrect. After further testing, Arctic Cat has verified that the compression specifications listed in Section 2, page 4 should be **corrected** to read **65-85 psi**. Please make this change in your manual. The correct specifications will be included in a following edition.

■ **NOTE:** Please be aware that when testing for engine compression, some pressure gauges may vary slightly. Also be aware that when testing an engine with low mileage, the compression may read on the low end due to the fact that the rings have not had time to seat.

Please advise all your service technicians of this important change.

Thank you for your cooperation and understanding in this matter.

Sincerely,

Product Service Department
Arctic Cat Inc.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1002