





SERVICE 		3
		B0000024

English 1 (1)

SB, Ignition cable, 2000-10

An improved ignition cable will be introduced during 2000 on all ignition systems.
The improved cable is marked with: **ALCATEL X**

The following ignition systems are affected:

503 13 85-02	Ignition system	3120XP
503 63 98-01	Ignition system	394, 395
503 90 12-01	Ignition system	254, 257, 262
503 90 14-01	Ignition system	61, 268, 55, 51
503 90 17-01	Ignition system	3120K
503 95 89-01	Ignition system	371K
503 96 24-01/06	Ignition system	372XP, 365, 362XP, 340, 345, 346XP, 350, 351
501 81 28-01	Ignition system	281, 288XP

