





SERVICE 		6
		B0100024

English 1 (1)

SB, 265 RX, Starter, 2001-05

The area around the bottom right screw hole (viewed from outside) on the starter housing has been reinforced. See diagram. Problems have been experienced with cracking around this screw hole in certain situations, particularly when the screws that hold the starter housing were not correctly tightened.

The reinforced starter housing has improvement code Q.

The article number is the same as before, 502 00 15-02.

Introduced from serial number: 01.1200001

