





SERVICE 		10
		B0100041

English 1 (1)

SB, 325 HDA 55, Tube, 2001-09

When fitting the tube to the 325HDA55 it is very important that it is fitted the right way round. Fitting the tube incorrectly will cause serious damage to the drive shaft.

The end that has the bearing closest to it must be fitted to the cutter bar. This end is identified by two dots that are marked on the tube.

New part no.	Description	Excl. part no.	Remark
537 09 11-01	Tube		

