

SB, Rider ProFlex, Belt tensioner spring, 2003-08

The cause of the problem with broken springs and possible damage to the cutting unit strap is imbalance on the roller, part. no 506 92 89-01, for belt adjustment (see picture).

To rectify:
Order the new roller from stock and replace.

Spare part number: 506 92 89-01.

