

SERVICE 		7 B0400044
--	--	-----------------------------

SB, Rider, Articulated joint for hydrostatic wire, 2004-06

During checks at the assembly factory it has been found that the mounting for the front articulated joint for the hydrostatic wire may be fitted with too low a torque. This could result in play occurring in the hydrostatic wire.

The torque must be checked before delivery or when servicing is carried out.

The recommended torque is 5–7 Nm.

