



For a better co-ordination of the different languages for service bulletins we have now started on a new number series.

The previous bulletin has number 10: X 84.039-96.

Pour mieux coordonner les bulletins de service en différentes langues, nous avons commencé une nouvelle série de Nos.

Le bulletin antérieur a le N° 10: X 84.039-96.

MODEL } **165 R**
MODÈLE }

SHORT CIRCUIT DEVICE

A shrink tubing has been added over the spade connector on the short circuit lead from the ignition system. This is done in order to eliminate any jumping sparks.

Reference No.: 502 03 85-01.

The new short circuit device is introduced on 165 R from serial number 4420526.

SUPPORT FLANGE

Field reports tell that the support flange has insufficient contact against the blade. Therefore we have introduced a support flange with correct surface contact in our production.

Reference No.: 502 03 14-02.

The new support flange is introduced from serial number 4420456.

FIL DE COURT CIRCUIT

Sur le contact AMP du fil de court circuit sortant de l'allumage nous avons monté une durite de serrage afin d'éviter un éventuel éclat d'étincelle.

N° de réf.: 5020385-01.

Cette nouvelle durite de serrage est montée sur la 165 R à partir du numéro de série 4420526.

BRIDE D'APPUI

Selon les rapports du terrain, la surface d'appui de la bride n'a pas été assez grande. Afin d'y remédier nous avons introduit une meilleure bride.

N° de réf.: 5020314-02.

La nouvelle bride est montée à partir du numéro de série 4420456.