





<b>SERVICE</b> 		<b>8</b>
		X 87.106-26

MODEL **40**

THROTTLE CABLE

In order to prevent water to penetrate down between cable and cover, which in extreme cases may cause the cable to freeze, the attachment to the throttle cable is changed in the rear handle. At the same time the throttle cable receives an extended cover.

<u>New Ref. No.</u>	<u>Description</u>	<u>Excluded Ref. No.</u>	<u>Remark</u>
503 50 52-02	Handle half with throttle cable compl.	503 10 53-01	
506 01 40-03	Throttle cable compl.	506 01 40-02	Remains as a spare part

The change was introduced from serial number 7121299.

