





SERVICE 		1
		X 88.124-96

MODEL } 254
MODÈLE }

We have in our production increased the material thickness around the screw holes for the cylinder cover on the crankcase.

The Ref. No. for the crankcase is unchanged.

The change was introduced during spring -88 from the marking N on the drive side and R on the flywheel side of the crankcase.

Dans le carter moteur il y a maintenant plus de matériau autour des trous pour les vis du capot de cylindre.

Le carter conserve sa référence.

Cette modification a été introduite au cours du printemps. Le nouveau carter est distingué par les repères N sur le côté embrayage et R sur le côté allumage.