





SERVICE 		8
		X 90.121-26

MODEL 40

Cylinder cover

The new Phelon ignition module has made it more difficult to mount the cylinder cover, when doing service work.

We have made a modification to reduce this disadvantage. (See illustration)

The change is introduced from serial number 0170196.

