





SERVICE 		1
		X 91.132-26

MODELS 40/45

CRANKSHAFT SEAT COMPL.

We have introduced a new crankshaft seat compl.
 The new crankshaft seat has a sealing at the contact surfaces towards the crankcase resp. the cylinder. This means a simplification when servicing because there is no need for any sealing compound.

New Ref. No.	Description	Excluded Ref. No.
506 05 65-02	Crankshaft seat compl.	506 05 65-01

The change is introduced from serialnumber: 40- 1050001
 45-1061401

