





SERVICE 		2 X 95.002-26
---	--	-------------------------

Model 250RX

Piston 502 17 39-01

There is a risk of seizing if this machine is used primarily for grass clearing while running for longer periods at max. speed. Especially in hot conditions. During servicing when this problem has occurred, we therefore recommend changing to piston, 502 27 35-01 (250 R). This gives somewhat lower compression.

502 17 39-01 (RX)
502 27 35-01 (R)

