



SERVICE 		14
		X 95.002-26

Model 240/245

Crankshaft seat

We have noticed a leaking problem with the existing crankshaft seat ref. number: 502 12 21-01.

To cure the problem we are now using the 40/45 crankshaft seat with steel sleeves at the cylinder mounting holes.

The 40/45 seat has softer material at the edge and is by that more flexible.

The steel sleeves is for positioning the crankshaft exactly to align the clutch.

New Ref. No.	Description	Excl. Ref. No.	Remark
502 12 21-02	Crankshaft seat	502 12 21-01	

Introduced from serial number:	240R	525 0377
	245R/RX	535 0176

