



# SERVICE BULLETIN 125

## INFORMATIONAL ADDENDUM

**REVISION DATE:** August 31, 1999

**SUBJECT:** ADDENDUM - Service Bulletin 125 has been amended.

**MODELS:** Only those listed below.

The following list of model and specification engines, **ARE THE ONLY ONES AFFECTED BY** the potentially defective fuel line:

H35-45492Y	HMSK105-159904A	HMSK90-156533D	OHH60-71112C	OHSK55-69516C
H35-45717Y	HMSK105-159906A	HSK40-55510V	OHSK100-221606A	OHSK55-69519C
H35-45746Y	HMSK105-159907A	HSK60-76005C	OHSK100-221607A	OHSK55-69520C
HM100-159298P	HMSK110-159953A	HSK60-76011C	OHSK110-221701A	OHSK70-72500B
HM100-159350P	HMSK110-159957A	HSK60-76012C	OHSK110-221703A	OHSK70-72501B
HM100-159351P	HMSK110-159958A	HSK60-76013C	OHSK110-221708A	OHSK70-72505B
HM100-159383P	HMSK110-159962A	HSK60-76016C	OHSK110-221709A	OHSK70-72506B
HM100-159400P	HMSK80-155527V	HSK70-130208U	OHSK110-221710A	OHSK70-72507B
HM80-155522S	HMSK80-155545V	HSK70-130283U	OHSK110-221712A	OHSK70-72508B
HM80-155593S	HMSK80-155635V	HSK70-130302U	OHSK110-221713A	OHSK70-72511B
HM80-155653S	HMSK80-155640V	HSSK50-67002S	OHSK120-223601A	OHSK70-72512B
HM80-155664S	HMSK80-155645V	HSSK50-67261S	OHSK130-223801B	OHSK70-72513B
HMSK100-159001W	HMSK80-155667V	HSSK50-67366S	OHSK130-223802B	OHSK80-221202A
HMSK100-159295W	HMSK80-155668V	HSSK50-67368S	OHSK130-223803B	OHSK90-221401A
HMSK100-159303W	HMSK80-155669V	HSSK50-67390S	OHSK130-223804B	OHSK90-221404A
HMSK100-159426W	HMSK80-155670V	HSSK50-67395S	OHSK130-223808B	OHSK90-221406A
HMSK100-159432W	HMSK80-155671V	HSSK50-67401S	OHSK130-223814B	OHSK90-221407A
HMSK100-159433W	HMSK80-155672V	LEV115-350126D	OHSK130-223815B	OHSK90-221408A
HMSK100-159434W	HMSK80-155684V	OHH55-69040E	OHSK130-223816B	OHSK90-221410A
HMSK100-159439W	HMSK85-155902A	OHH55-69058E	OHSK130-223818B	OHSK90-221411A
HMSK100-159440W	HMSK90-156519D	OHH55-69073E	OHSK130-223819B	OHSK90-221412A
HMSK100-159441W	HMSK90-156528D	OHH55-69085E	OHSK50-68500C	OHSK90-221413A
HMSK105-159903A	HMSK90-156532D	OHH55-69103E	OHSK55-69513C	OHHV130-206854C
				VLV126-502052E

Note these units:

- are equipped with the Tecumseh supplied, in line shutoff valve.
- were produced between May 1, 1999 and August 21, 1999.
- are principally found on snow throwers, however 5% are on chore product specifically, log splitters, post hole diggers and chipper shredders.

### Marking updated product" (Change effective immediately)


Please mark all updated product with a **"0" ZERO** in the location referenced on the following page of this addendum. If necessary, purchase the appropriate punch and place the description and cost on your first warranty claim.

**Tracking Repaired Units:** Effective immediately it is **CRITICAL** you record the equipment manufactures unit serial number(s) as par of the procedure. If the space provided on the ESA-157 warranty claim for is insufficient you can attach a separate sheet listing these numbers.

# SERVICE BULLETIN 125


**INFORMATIONAL**

## ADDENDUM



### REPAIR UNIT LOCATION OF IDENTIFYING STAMP MARK "0"


Top View



STAMP "0" ON MUFFLER STRAP


**HM/HMSK80-110**

Side View



STAMP "0" ON FLANGE


**LEV115**



STAMP "0" ON FLANGE


**VLV126**

Top View




STAMP "0" ON MUFFLER STRAP

**H/HS/HSSK35-70**



STAMP "0" ON LIFT STRAP

**OHSK80-130**



STAMP "0" ON LIFT STRAP

**OHSK50-70**

Note: Some updated units will be identified as follows: The "0" will be stamped into the engine mounting flange, underneath the fuel tank, next to the oil drain plug.