

SERVICE
BULLETIN
404
4 CYCLE



ISSUED: February 1997

SUBJECT: OHH/OHSK Composite Camshaft Replacement

MODELS OR TYPES AFFECTED: OHH/OHSK 50 - 60 with a DOM (Date of Manufacture) of **7048** and higher.

A running change has been made to the camshaft on OHH/OHSK 50 - 60 engines with a D.O.M. (Date of Manufacture) of 7048 and higher. The result of this change is a substantial overall noise reduction in the engine.

A composite camshaft replaces the cast iron type. If the cast iron cam is replaced for any reason, new valve springs **MUST** be installed or lobe damage will occur. All parts needed for this direct replacement camshaft come in kit part number 37040.

This kit includes:

- (1) Camshaft
- (1) Yoke 36701
- (1) Spring 36702
- (2) Valve springs 37039

Refer to the Instruction Sheet included in the kit or the Overhead Valve Mechanic's Handbook (695244A) for disassembly and assembly procedures for proper removal and installation of camshaft and valve springs.