

Service Advisory

W-146A

ZERO TURN

Models Affected:

ZT-42 (17BA5A4G790, 17AA554G790, 17AJ2ACG090).

W.O.P.

ZT-4200 (17AC2ACG790).

ZT-50 (17BA5A7P790, 17AA557P790, 17AK2ACP090, 17AK2ACP290, 17BK2ACP090).

ZT-5000 (17BK2ACP090).

Models Affected:

RZT-42 (17AJ2ACG597, 17AJ2ACG897).

Columbia

RZT-50 (17AK2ACP597, 17BK2ACP597,17AK2ACP897).

Serial Number Range Affected:

1B175G through 2009. (February 17, 2005 through 2009).

Date:

September 27, 2006 Revised On August 14, 2009 (Destroy All Previous Copies).

Subject:

Failure Of Welds Of The P.T.O. Clutch Torque Bracket To The Frame.

IMPORTANT ATTENTION PARTS MANAGER ATTENTION SERVICE MANAGER

SOLUTION:

If a failure of the welds on the P.T.O. Clutch Torque Bracket occurs the replacement of the frame is *No Longer* needed. A P.T.O. Clutch Torque Bracket **603-04290B-0637** is now available as a bolt on service replacement part.

NOTE: 603-04290B-0637 replaces 603-04290A-0637.



Please Make a note of the part number **603-04290B-0637** P.T.O. Clutch Torque Bracket in your parts IPL or business system.

Warranty: Normal warranty terms apply. Indicate Service Advisory **W-146A** and (**See Note Below)** for the original failed part to list on the claim. Repair time allowance is 1.0 Hrs.

NOTE: *Part Numbers for the frame that can be listed on the claim for the original failed part are,* 603-04303, 603-04303B, 603-04303C, 603-04303E or 603-04691.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial