



Service Bulletin

Date: August 29, 2005

Product Line: ATV

Bulletin No: 2006-2-02

Subject: Ignition Coil Isolator

Affected Models/VIN:

All 2005 650 H1 LE ATV's

Condition: It has been determined that the ignition coil, on rare occasions, may produce intermittent spark causing the ATV to lose power.

■ **NOTE:** Testing of this condition has determined that the intermittent spark occurs only when the ATV is operating in cold temperatures (0° F and below).

Solution: Install Ignition Coil Isolator Update Kit (p/n 0437-046) per instructions included in the kit.

Parts: Order an appropriate number of Ignition Coil Isolator Kit (p/n 0437-046) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.2 hr will be paid per affected ATV.
Claim: Enter BA200602 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected ATV. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on ATV's with warranty claims is important.

ATTENTION

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to August 29, 2006. All warranty claims directly related to this issue will not be honored after August 29, 2006.
--