



Service Bulletin

Date: January 14, 2005

Product Line: Snowmobile

Bulletin No: 2005-1-06

Subject: Improperly Tightened Torque Bracket Cover

Affected Models/VIN Range:

All 2005 ZR 900 models

2005 F5 and F7 models within the VIN Range of 4UF05SNW15T115828 - 4UF05SNW05T125539

■ **NOTE:** Only models equipped with the ACT drive system are affected.

Condition: It has come to our attention that the three screws securing the torque bracket cover may not have been tightened properly and may come loose.

Solution: Remove the screws, apply blue Loctite #243 to the screws, reinstall the screws, and tighten to the proper torque factor. Be sure to refer to the specific instructions enclosed with this bulletin.

Parts: Not Applicable (no parts are needed).

Warranty: A total labor allowance of 0.2 hr will be paid per affected snowmobile.
Cat Tracker Claim: Enter BS200506 in the Complaint section.
Manual Claim: Enter 0506 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected snowmobile. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on snowmobiles with warranty claims is important.

ATTENTION

Completing the necessary service work as soon as possible will eliminate the possibility of related damage to the snowmobile. To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to January 14, 2006. All warranty claims directly related to this issue will not be honored after January 14, 2006.

