

Date: March 28, 2003

Product Line: Snowmobile

Bulletin No: 2003-1-43

Subject: Pintle Hitch Latch

Service Bulletin

Affected Models / VIN: All 2003 Bearcat Wide Track Models Model No. S2003BCFWTUSS Model No. S2003BCFWTOSS (International)

| Condition : | It has been determined that the existing hitch latch on the affected models does not meet Arctic Cat standards and <u>must</u> be replaced. |
|--------------------|--|
| Solution: | Replace the existing hitch latch with new Hitch Latch (p/n 2706-503). Discard the existing hitch latch. |
| Parts: | Order an appropriate number of Hitch Latch (p/n 2706-503) through normal parts-ordering chan- nels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form. |
| | ■ NOTE: Parts will be available in the near future. |
| Warranty: | A labor allowance of 0.2 hr will be paid per affected snowmobile. |

Warranty: A labor allowance of 0.2 hr will be paid per affected snowmobile. Only one vehicle identification number (VIN) can be entered per claim. CatTracker Claim: Enter BS200343 in the Complaint section. Manual Claim: Enter 0343 in the Complaint section.









®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701

0303