



# Service Bulletin

**Date:** December 20, 2002

**Product Line:** Snowmobile

**Bulletin No:** 2003-1-27

**Subject:** Handlebar Pad Wrap

**Affected Models / VIN:**

All 2003 ZL Models (see list below)

**ZL 800 EFI SS**

Model No. S2003ZLHSSUSB (Black)

Model No. S2003ZLHSSUSM (Silver)

**ZL 800 EFI esr**

Model No. S2003ZLHSEEUSB (esr Black)

Model No. S2003ZLHSEEUSM (esr Silver)

**ZL 600 EFI**

Model No. S2003ZLDEFUSB

Model No. S2003ZLDEEUSB (esr Black)

Model No. S2003ZLDEEUSM (esr Silver)

**ZL 600 EFI SS**

Model No. S2003ZLDSSUSB (Black)

Model No. S2003ZLDEAUSB (esr Black)

Model No. S2003ZLDSSUSM (Silver)

Model No. S2003ZLDEAUSM (esr Silver)

**ZL 550**

Model No. S2003ZLCLCUSB

Model No. S2003ZLCERUSB (esr Black)

Model No. S2-3ZLCERUSM (esr Silver)

---

**Condition:** It has been determined that the existing handlebar pad wrap does not meet Arctic Cat standards (the pad may fade if exposed to direct sunlight) and must be replaced.

**Solution:** Replace the existing handlebar pad wrap with Handlebar Pad Wrap (p/n 0705-898).

**Parts:** Order an appropriate number of Handlebar Pad Wrap (p/n 0705-898) through normal parts ordering channels. Your dealership Parts-Account will be charged and then credited upon receipt of a Warranty Claim Request form.

**Warranty:** A labor allowance of 0.2 hr will be paid per affected snowmobile.

Only one vehicle identification number (VIN) can be entered per claim. Do not submit a group claim.

CatTracker Claim: Enter BS200327 in the Complaint section.

Manual Claim: Enter 0327 in the Complaint section.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1202