Homelite

Consumer Products, Inc. Anderson, SC.

Service Level MANDATORY

TECHNICAL SERVICE BULLETIN

Product – UT10927 16" 38cc, UT10942 20" 45cc, UT10946 18" 45cc

<u>Identification</u> – Homelite Chain Saw

<u>Condition</u> – When servicing or repairing the chain brake assembly the installation of the service components are required to comply with the improved chassis and brake band design.

Remove the original parts:

UP08569	Chassis
UP08097	Chain Brake Band Kit
UP04223	Chain Brake Link
UP08723	Compression Spring

Service Components Required

1 ea. 985028001	Chassis Assembly
1 ea. 985030001	Brake Band
1 ea. 985021001	Brake Band Cover
3 ea. 82513	Screw
1 ea. 984897001	Chain Brake Link
1 ea. 985240001	Compression Spring

Service Procedures

Replace service components as directed.

Submit warranty claim using warranty code ------ HCS-SVB2
Warranty claim compensation ------- 1 hour - based on Hourly Shop Rate

For technical assistance contact Homelite technical support at 1-800-242-4672

Page 1 of 1

UT10927 / UT10942, UT10946 07/20/04