





SERVICE 		1
		B0200039

English 1 (1)

SB, 346, 351, Crankcase, 2002-06

The crankcase has been reinforced and modified.

The crankcase has the following casting codes: clutch side AA, flywheel side Z.

The crankcase gasket has also been replaced, and the part number of the gasket kit has therefore changed.

New part no.	Description	Excl. part no.	Remark
537 17 19-03	Crankcase assy.	537 17 19-01	
503 94 28-02	Gasket kit	503 94 28-01	

Introduced from serial number:	346	020500401
	351	020700001

