





SERVICE 		6
		B0300030

English 1 (1)

SB, 340, 345, 346, 350, 353, Winter cover, 2003-03

Due to a modification to the starter, see bulletin B0300006, the winter cover must also be modified. This also requires a minor adjustment to the starter.

If the winter cover is a loose fit, file off the lugs as shown in the diagram below.

In order to block the air injection nozzle one of the fins on the starter must be cut off as shown in the diagram below.

New part no.	Description	Excl. part no.	Remark
537 04 28-02	Winter cover	537 04 28-71	

