




SERVICE 		10
		X 94.154-26

Model **225/232**

Clutch cover

There have been a small number of fractures on shafts by the connection to the clutch cover. To prevent this, the clutch cover has been slotted by the clamping joint to provide a smoother transition between the rigidity of the clutch cover and the shaft.

Introduced into production from week 26.

