





SERVICE 		3
		B9900020

English 1 (1)

SB, 240, 245R, 245RX, 51, 55, 40, 45, 49, Starter pawls, 1999-04

Some starter pawls have been found to break during bending because they have the wrong bend radius. This has now been corrected.

The modified starter pawls are marked with the number three (3) (see diagram). The starter pawls also have a new reference number.

New ref. no.	Description	Excl ref. no.	Remarks
503 71 02-03	Starter pawl	503 71 02-02	

