



N9901007

1999-05

Engineering Services

Page 1 (1)

MODELS: 136/141 & 36/41

SUBJECT: Tight or Poor Fitting Fuel Caps

ACTION REQUIRED:

Replace fuel cap with new, longer reach cap.

New Part # 530 07 12-66

Description fuel cap

Repl. Part # 501 81 96-02*

^{*} still available as a spare part