



Service Advisory

TRACTOR

W-141

Models Affected: GT 950H (14A9816P790)
 GT 2150 (14AJ816H190, 14BJ816H190, 14A6816H190)
 GT 2550 (14AZ816P190, 14BZ816P190, 14AZ816K190, 14A9816K190)
 GT 2550H (14A9816K790)

Serial Number Range Affected: 2005 Production GT 950H
 2000 - 2003 Production GT 2150
 2000 - 2003 Production GT 2550
 2004 Production GT 2550H

Date: **July 12, 2006**

Subject: **753-05398 Service Replacement.**

IMPORTANT

ATTENTION PARTS MANAGER

ATTENTION SERVICE MANAGER

PURPOSE: The 618-0379 (918-0379) Hydrostatic Transmission, with splined axle shafts and wheel hubs secured with a nut, will no longer be available. When needing to replace as a complete assembly, order a **753-05398** Service Replacement Kit. The contents of this kit are listed below.

753-05398

Service Replacement Kit

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	618-04329	1	Transmission Assembly: Hydro
2	618-04317	2	Hub Assembly: Wheel: Double D
3	736-0227	2	Washer: Flat: .390" x 1.500" x .134"
4	710-3119	2	Screw: Hex: 3/8-16 x .750" : GR5: Lock

NOTE: Save this Advisory or the Instruction sheet form # 769-02128. Refer to it when ordering replacement parts.

This is being released for informational purposes only.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial