Service Bulletin

Date: September 24, 2002

Product Line: Snowmobile

Bulletin No: 2003-1-07

Subject: Piston Upgrade / 2001 800 cc Twin Engines

Affected Models / VIN:

2001 Mountain Cat 800
Model No. S2001MCHCAUSB
VIN Range: Not Applicable

2001 ZL 800 esr
Model No. S2001ZLHERUST (Illusion)
VIN Range: Not Applicable

2001 Mountain Cat 800
Model No. S2001MCHLEUSG (LE-Green)
VIN Range: Not Applicable

2001 ZR 800
Model No. S2001ZRHCAUSG
VIN Range: Not Applicable

2001 Mountain Cat 800
Model No. S2001MCHLEUSB (LE-Green)
VIN Range: Not applicable

2001 ZR 800
Model No. S2001ZRHLEUSB (LE)
VIN Range: Not Applicable

2001 Mountain Cat 800
Model No. S2001MCHLEOSG (International)
VIN Range: Not Applicable

2001 ZR 800
Model No. S2001ZRHCAOSG
VIN Range: Not Applicable

2001 ZL 800 esr
Model No. S2001ZLHERUSB
VIN Range: Not Applicable

Condition: It has been determined that the original pistons in the affected snowmobiles do not meet Arctic Cat standards. Because of this condition, Arctic Cat is offering a Piston Update Kit at no charge to registered owners of the affected snowmobiles.

Solution: Install Piston Update Kit (p/n 0637-223) according to the instructions in the kit.

■ **NOTE: All registered owners of the affected snowmobiles will be sent a letter concerning this issue. They will be instructed to contact an authorized Arctic Cat snowmobile dealership to have the necessary service work completed.**

Parts: Order an appropriate number of Piston Update Kit (p/n 0637-223) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.8 hr will be paid per affected snowmobile.

Only one vehicle identification number can be entered per claim. Do not submit a group claim.

CatTracker Claim: Enter BS200307 in the Complaint section.

Manual Claim: Enter 0307 in the Complaint section.

■ **NOTE: Please remember that Arctic Cat has a 90-day holding period for all affected parts starting on the date of repair.**