



Service Bulletin

Date: October 21, 2005

Product Line: Snowmobile

Bulletin No: 2006-1-04

Subject: Driven Pulley Sheave Adjuster

Affected Models/VIN Range:

2005 Firecat Models (excluding those with reverse) and 2004/2005 ZR 900 Models

Condition: It has come to our attention that the driven pulley sheave adjuster may come loose during the operation of the snowmobile. If the sheave adjuster loosens, the drive belt will tighten. This condition may cause the snowmobile to creep forward while idling. A tightened belt may also cause difficult starting.

Solution: Install new Sheave Adjuster Update Kit (p/n 0637-291) per instructions included in the kit.

Parts: Order an appropriate number of Sheave Adjuster Update Kit (p/n 0637-291) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.2 hr will be paid per affected snowmobile. Enter BS200604 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected snowmobile. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on snowmobiles with warranty claims is important.

ATTENTION

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to October 21, 2006. All warranty claims directly related to this issue will not be honored after October 21, 2006.

