



# Service Bulletin

**Date:** February 14, 2001

**Affected Model(s):** 2001 Mountain Cat 800  
2001 Mountain Cat 800 LE (Black)  
2001 Mountain Cat 800 LE (Green)

**Bulletin No:** 2001-1-20

**VIN:** Not Applicable

**Product Line:** Snowmobile

**Subject:** Belly Pan & Hood Foam  
(Sound Reduction)

**Condition:** Arctic Cat is very concerned about complying with all aspects of the SSCC certification program. Arctic Cat has always been an advocate of snowmobile safety and environmental concerns. During a recent snowmobile certification audit, the affected models listed above did not comply with the snowmobile sound emissions requirements.

**Solution:** In order to comply with the SSCC certification program, it is necessary for you to install Sound Emission Update Kit (p/n 0637-212) on all affected models sold through your dealership. Parts and installation instructions will be included in the kit.

**Parts:** Order the appropriate number of Sound Emission Reduction Update Kit (p/n 0637-212) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Form(s) from your dealership.

**Warranty:** A labor allowance of 0.3 hr will be paid per affected snowmobile.  
A group Warranty Claim Form of up to 9 vehicle identification numbers (VIN) will be accepted.  
Enter 2001-1-20 in the Complaint section of the Warranty Claim Form (s).

■ **NOTE:** This bulletin expires February 14, 2003.



# Bulletin de service

**Date:** Le 14 février 2001

**Modèle(s) Concerné(s):**

Mountain Cat 800 2001

Mountain Cat 800 LE (Noir) 2001

Mountain Cat 800 LE (Vert) 2001

**Numéro de bulletin:** 2001-1-20

**NIV:** Ne s'applique pas

**Ligne de production:** Motoneige

**Objet:** Cuvette & mousse de capot  
(Réduction du son)

**Condition:**

Arctic Cat est très soucieux au sujet de la réglementation sur tous les aspects du programme de certification SSCC. Arctic Cat a toujours été défenseur auprès de la sécurité en motoneige et des questions d'ordre environnementales. Lors d'une récente vérification de certification en motoneige, les modèles concernés cités en rubrique ne répondent pas aux exigences demandées pour les émissions de sons.

**Solution:**

De manière à se rendre conforme au programme de certification SSCC, il est nécessaire pour vous d'installer la trousse de mise à jour d'émission de son (n/p 0637-212) sur tous les modèles vendus à votre concession. Les instructions d'installation et de pièces seront incluses dans la trousse.

**Pièces:**

Veuillez commander le nombre approprié de trousse de réduction d'émission de son (n/p 0637-212) en passant par les voies de commande normales. Votre compte de pièces de concession sera facturée et ensuite crédité lors de la réception du(des) formulaire(s) de réclamation de garantie provenant de votre concession.

**Garantie:**

Une allocation de main-d'oeuvre de 0,3 h sera payée par motoneige concernée.

Un formulaire de réclamation de garantie en groupe ayant jusqu'à 9 numéros d'identification de véhicule (NIV) sera accepté.

Inscrivez 2001-1-20 à la section Plainte sur le(s) formulaire(s) de réclamation de garantie.

■ **REMARQUE:** Ce bulletin prendra fin le 14 février 2003.



Imprimé aux États-Unis



® TM Marques déposées d'Arctic Cat Inc., Thief River Falls, MN 56701



0201