



# Service Bulletin

**Date:** December 9, 2002

**Product Line:** Snowmobile

**Bulletin No:** 2003-1-21

**Subject:** Air Silencer Breather Hose Leakage

**Affected Models / VIN:**

All 2003 Bearcat Wide Track Models (see list below)

Model No. S2003BCFWTUSS

VIN Range: 4UF03SNW23T169593 - 4UF03SNWX3T170426

Model No. S2003BCFWTOSS (International)

VIN Range: 4UF03SNW13T168774 - 4UF03SNW03T169592

**Condition:** It has been determined that Air Silencer Assembly Breather Hose (p/n 0610-489) may expand when in contact with oil and gas. This condition may cause the hose to leak a small amount of oil onto the air silencer assembly.

**Solution:** Install Clamp (p/n 0623-486) onto the breather hose-to-air silencer assembly connector.

**Parts:** Order an appropriate number of Clamp (p/n 0623-486) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

**Warranty:** A labor allowance of 0.2 hr will be paid per affected snowmobile.  
Only one vehicle identification number (VIN) can be entered per claim.

Do not submit a group claim.

CatTracker Claim: Enter BS200321 in the Complaint section

Manual Claim: Enter 0321 in the Complaint section



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1202