



Service Advisory

Date: September 12, 2002

Product Line: Snowmobile

Advisory No: SAS302

Subject: Oil Level Sender

Affected Models/VIN:

2003 Firecat 500

It is important when setting up and running a 2003 Firecat 500, that the oil tank be completely filled. If the tank is not completely filled, damage to the oil level sender and oil tank may occur.

⚠ CAUTION

Do not start or run any 2003 Firecat 500 without first filling the oil tank.

We will send repair information concerning this condition within the next few days.

■**NOTE: Some Firecat 500's will be shipped with the oil level sender unplugged to protect the snowmobile from this condition. Please leave the oil level sender unplugged until you receive repair information that will follow this advisory.**

The only action you need to take at this time is to be sure to not start or run a Firecat 500 without first completely filling the oil tank. Bulletin information will follow this notice within a few days.

Thank you for your cooperation in this matter.

Sincerely,

Product Service Department
Arctic Cat Inc.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0902