





SERVICE 		8
		B0100018

English 1 (1)

SB, 252 RX, 250 R, Throttle cable-cable guard, 2001-03

The cable conduit has now been fitted with two stop sleeves on 252RX and one stop sleeve on 250R to prevent unintentional. On both models one stop sleeve is positioned on the conduit and is supported by a wall inside the cable guard. See figure.

252RX also has a stop sleeve on the other end of the cable conduit and which is supported by an existing wall on the throttle handle. See figure. This locks the preventing it from being pulled out of position.

Both cables with stop sleeves and the cable guard with wall must be fitted to give satisfactory protection against unintentional throttle action.

The new parts can also be fitted on older machines.

Introduced into production during week 00.45 for the throttle cable and week 00.38 for the cable guard.

New part number	Description	Old part number	Remarks
537 02 42-03	Throttle cable	537 02 42-01	252RX
537 02 42-04	Throttle cable	537 02 42-02	250R
502 20 68-02	Cable guard	502 20 68-01	252RX/250R

