



<b>SERVICE</b> 		<b>1</b>
		<b>B0100027</b>

English 1 (1)

## SB, 346XP, 351, Crankcase, 2001-03

Bigger screws have been introduced for the movement limiters to achieve a more effective installation of them. The holes in the crankcase are also bigger. The new screws do not fit in older crankcases, and vice versa.

Brought into production from serial number: 351 994400251  
 346XP 994200501

New ref. no.	Description	Excl. ref. no.	Remarks
503 21 51-01	Screw	503 21 88-20	*
503 85 69-75	Crankcase	503 85 69-73	

\* Remains as spare part

