





<b>SERVICE</b> 		<b>1</b> <b>B0100030</b>
--	--	-----------------------------

English 1 (1)

## SB, 372 XP, 365 Special, 362 Special, Crankshaft, 2001-06

### Crankshaft replacement

When a crankshaft is replaced it is very important that all the other components that affect its balance are replaced at the same time. To make this easier we have put together a special kit, art. no. 503 74 87-01.

New part no.	Description	Excl. part no.	Remark
503 74 87-01	Crankshaft kit	503 72 91-78	
	Ball bearing	738 22 02-25	*
	Needle bearing	503 25 56-01	*
	Sleeve	503 77 91-01	*
	O-ring	503 26 30-19	*
	Clutch assy.	503 74 44-01	*

\* Still available as spare part

