





SERVICE 		1
		B0100038

English 1 (1)

## SB, 335 XPT, Cutting equipment, 2001-06

To permit use of 1/4" cutting equipment a suitable clutch drum and oil pump pinion are now available as spare parts.

New part no.	Description	Excl. part no.	Remark
537 07 91-71	Clutch drum		
503 78 92-03	Oil pump pinion		

