

SB, 325 HS 75, 325 HS 99, Puller, 2001-09

The frame bearing on the flywheel side of the crankshaft on the 325HS is pressed into place. A puller is now available for removing this bearing.

For further information see Workshop Manual 101 90 73-26.

New part no.	Description	Excl. part no.	Remark
531 00 48-67	Puller		

