



Service Bulletin	B0103003
	2001-7

Subject: Plastic Fuel Tanks on all Husqvarna Turf Care ZT Riding Mowers.

Effected Model/Serial Numbers:

SMALL FRAME RIDER

- 968999157 - ZTHKH4818 S/N's 003700001 thru 012700211
- 968999158 - ZTHKH4820 S/N's 003700016 thru 012700100
- 968999167 - ZTHKW4218 S/N's 003700026 thru 012700500
- 968999168 - ZTHKW4818 S/N's 003700046 thru 012700505
- 968999169 - ZTHKW4821 S/N's 003700032 thru 012700213
- 968999170 - ZTHQL4218 S/N's 010200001 thru 012700232
- 968999172 - ZTHQL4221 S/N's 010200001 thru 012700045

LARGE FRAME RIDER (Gen II)

- 968999159 - ZTH5221KAA S/N's 003700022 thru 012700347
- 968999160 - ZTH5223KAA S/N's 003700001 thru 012700303
- 968999161 - ZTH5223KOA S/N's 003700001 thru 012700194
- 968999162 - ZTH5223KOLA S/N's 003700001 thru 012700096
- 968999163 - ZTH5225KOA S/N's 003700001 thru 012700158
- 968999164 - ZTH6123KOLA S/N's 011400001 thru 012700006
- 968999165 - ZTH6125KOA S/N's 003700002 thru 012700753
- 968999166 - ZTH6125KAA S/N's 003700001 thru 012700713
- 968999171 - ZTH6125KAA S/N's 010200001 thru 012700151
- 968999173 - ZTH5225KAA S/N's 010200001 thru 012700095

Service Information: There have been reported instances from the field that plastic fuel tanks from our current vendor may contain plastic molding shavings. These shavings will plug the fuel filter very rapidly, causing erratic engine operation. Close inspection of fuel tanks in new inventory confirms this finding.

Effective immediately, all fuel tanks on new Husqvarna Turf Care ZT Riding Mowers in dealer whole goods inventory should be inspected, vacuumed, blown out, or otherwise flushed, before gasoline is added. We have found vacuuming to be the most effective in removing these dry particles.

Parts Information: Does not apply.

Warranty Information: One half hour dealer labor, 15 minutes per tank, will be authorized for the inspection and cleaning of fuel tanks on new Husqvarna Turf Care ZT Riding Mower whole goods inventory.

Normal warranty will apply to those units in the field for fuel filter replacement if they should become plugged from plastic shavings.