





SERVICE 		4
		B0200057

English 1 (2)

SB, 385, Tank valve, 2002-10

Two-way tank valve introduced on the above models.

The two-way valve has the following features:

- Controlled opening pressure in both directions, which prevents excess of pressure or vacuum developing in the fuel tank and impairing engine operation.
- More resistant to clogging with dirt in comparison with “earlier” version of tank vent.
- More resistant to icing up during winter operation compared with “earlier” version of tank vent.
- Venting pressure 150–400 mbar.
- Opening pressure under vacuum, max. 115 mbar.

New part no.	Description	Excl. part no.	Remark
537 09 22-01	Tank valve	501 87 31-01*	*still available for other models
537 09 93-01	Connector	503 60 04-01*	
501 76 83-05	Hose 110 mm**		



Introduced from serial number: 385 023500061

NOTE!

Compressed air must not be used for cleaning or pressure testing as this will damage the valve components.

** Only fit the hose between the valve and filter bend on saws without carburettor heating.



SERVICE 		4 B0200057
--	--	-----------------------------

English 2 (2)

