





<b>SERVICE</b> 		<b>4</b>
		<b>B0200070</b>

English 1 (2)

## SB, 346, Carburetor, 2002-10

A mechanical catch has been introduced for the choke valve to ensure a better seal between the carburetor housing and choke valve and to improve starting abilities.

The paper pump gasket for the carburetor assembly has been replaced with a rubber gasket.

New and old parts are fully compatible.

HDA 197 introduced from serial number: 346 024100601

<b>New ref. no.</b>	<b>Description</b>	<b>Excl. ref. no.</b>	<b>Remark</b>
503 28 18-14	Carburetor HDA 197	503 28 18-06	
537 15 81-01	Spring	503 56 25-01	
537 15 82-01	Lever	504 86 04-08	
537 15 79-01	Choke shaft	503 94 53-01	
537 15 80-01	Lever		
501 46 85-01	Choke stop ball		
501 46 84-01	Choke stop spring		

