



<b>SERVICE</b> 		<b>2</b>
		<b>B0300059</b>

## SB, 336, 338 XPT, 339 XP, 357 XP, Correction of hose assembly, 2003-10

The wrong hose has been packed with repair kit part no. 537 11 32-03. The hose that is included measures 26 mm, when it should be 48 mm.

This has been rectified. If you find a kit with the wrong hose please scrap the kit and order a new one.

