

Service Bulletin

B0301903 2003-11

Products: T-35 Trimmer Head Kit (531 30 01-94)


Subject: Incorrect Part Included in Service Kit

When ordering the new T-35 trimmer head part # 531 30 01-94, the trimmer head comes packaged as a kit that should also include a protective washer and an instruction sheet explaining proper installation.

We have received reports of some kits coming with a drive cup (B) instead of the protective washer (A). If you receive a kit containing a drive cup instead of a washer, the drive cup should be discarded and replaced in the kit with the protective washer part no. 537 24 09-01.

It is recommended that you check your inventory to identify and correct any of these kits that you may have purchased. Contact our technical service representatives to request replacement protective washers.

**Part No. Description** 537 24 09-01 Protective Washer



Page 1 of 1