





SERVICE 		5
		B0400026

English 1 (1)

## SB, 346 XP, 353, Air filter clip, 2004-03

The clip that secures the air filter touches the cylinder cover, which can cause the clip to break. Modifications are being made in production and to the stock of spare parts, but in the meantime the clip (503 96 27-01) can be modified as shown in the diagram below.

